

HoTT Updates	33505 GR-12S	33506 GR-12	33508 GR-16	33512 GR-24	33516 GR-32	33600 GPS	33601 Vario	33610 General Engine	33611 General Air	33620 Electric Air	33700 SMART-BOX	PC analysis software	Update main features
<p>The following steps are necessary:</p> <p>install USB drivers Update receiver, sensors and smart-box done with Graupner_Firmware_Update_Utility_Ver1.18.exe. Accessories required for the updates: # 7168.6, 7168.6A #, 2 # 3936.11, Receiver battery or receiver power supply</p>													
4754 mx-12													
<p>V3.2_4754_gr_12srx_3620.bin Initialize the transmitter after the update. Press and hold the END/RANGE Button and switch on the transmitter</p>			<p>33508_gr_rxd_3a10.bin or no update Initialize the receiver after the update. Press and hold the SET Button and switch on the receiver</p>			<p>33600_Gps_1p02.bin</p>	<p>33601_Var_1p12.bin</p>	<p>33610_33611_Gen_1p21.bin</p>	<p>33610_33611_Gen_1p21.bin</p>	<p>no update needed</p>	<p>33700_gr_slemetry_3a10.bin</p>	<p>HoTT-Manager 1.3x</p>	<p>Vario resolution 0.1m/s</p>
4755 mx-16													
<p>V3.2_4755_33301_gr_16srx_3620.bin Initialize the transmitter after the update. Press and hold the END/RANGE Button and switch on the transmitter</p>			<p>33508_gr_rxd_3a10.bin or no update Initialize the receiver after the update. Press and hold the SET Button and switch on the receiver</p>			<p>33600_Gps_1p02.bin</p>	<p>33601_Var_1p12.bin</p>	<p>33610_33611_Gen_1p21.bin</p>	<p>33610_33611_Gen_1p21.bin</p>	<p>no update needed</p>	<p>33700_gr_slemetry_3a10.bin</p>	<p>HoTT-Manager 1.3x</p>	<p>Vario resolution 0.1m/s</p>
33112 mx-12													
<p>33112_gr_mx-12_1v051_ab.bin new voice files must be loaded! Updates for # 33112 mx-12 done with software Radio_grStudio_Ver-S3.5 Essential Accessories: Mini-USB cable from # 7168.6 and 6460.3</p>			<p>33508_gr_rxd_3a10.bin or no update Initialize the receiver after the update. Press and hold the SET Button and switch on the receiver</p>			<p>33600_Gps_1p02.bin</p>	<p>33601_Var_1p12.bin</p>	<p>33610_33611_Gen_1p21.bin</p>	<p>33610_33611_Gen_1p21.bin</p>	<p>no update needed</p>	<p>33700_gr_slemetry_3a10.bin</p>	<p>HoTT-Manager 1.3x or Radio_grStudio_Ver-S3.5</p>	<p>new switchable tones for vario with headphones instead of the readers, faster telemetry, Smart-Box display option Telemetry displays with direct access by right CAP-Touch, Telemetry displays with large picture available, French menu language choice, Language files in German, English, French, Italian and Spanish available</p>
33116 mx-16													
<p>33116_gr_mx-16_1v051_ab.bin new voice files must be loaded! Updates for # 33116 mx-16 done with software Radio_grStudio_Ver-S3.5 Essential Accessories: Mini-USB cable from # 7168.6</p>			<p>33508_gr_rxd_3a10.bin or no update Initialize the receiver after the update. Press and hold the SET Button and switch on the receiver</p>			<p>33600_Gps_1p02.bin</p>	<p>33601_Var_1p12.bin</p>	<p>33610_33611_Gen_1p21.bin</p>	<p>33610_33611_Gen_1p21.bin</p>	<p>no update needed</p>	<p>33700_gr_slemetry_3a10.bin</p>	<p>HoTT-Manager 1.3x or Radio_grStudio_Ver-S3.5</p>	<p>new switchable tones for vario with headphones instead of the readers, faster telemetry, Smart-Box display option Telemetry displays with direct access by right CAP-Touch, Telemetry displays with large picture available, French menu language choice, Language files in German, English, French, Italian and Spanish available</p>